



## Roar Coatings Legacy Ceramic Coating Wipe-Off Chart

Temperature (°F)	Low Humidity (20–40%)	Moderate Humidity (40–70%)	High Humidity (80%+)
60	40–45 min	40–45 min	35–40 min
70	40–45 min	35–40 min	30–35 min
80	35–40 min	30–35 min	25–30 min
90 (not recommended)	25–30 min	20–25 min	20–25 min
100 (not recommended)	20–25 min	20–25 min	20–25 min

### ***Application & Removal Tips***

1. Apply evenly across the surface and allow to flash according to temperature and humidity.
2. Perform a test wipe to feel whether it still feels oily or has slight grab before full removal.
3. Use a two-towel removal method for best results: first towel removes 80%, second towel finishes the final 20%.
4. Preferred application temperature range: 60°F – 75°F.

Drier conditions extend flash times, while warmer and/or humid conditions shorten them.